

CELIER AVIATION	Bulletin Service Cat. Informative	Aircraft Type: Xenon RST Page 1 of 1
----------------------------	---	--

Gears in RST engine Gearbox.

Rotax engine manufacturer has produced a series of defective gears. Only 3 defective gears have been installed in Xenon RST, and we had no way to notice that during standard installation procedure. All the defective gears (with the part number tracking) have been located and exchanged under Rotax warranty. We apologize as well as Rotax for that problem. We do confirm that the original 912 UL gears are automatically replaced on all our RST to sustain the increased power.

We do recommend anyway to check during normal maintenance sessions the magnet screw installed on the gear box. Do not hesitate to contact us if you see any abnormal metal particles on the magnet, and or rattling noise of the gear box, when of course your idle is properly set at 1600 RPM.

Fly safe and do carefully all your checks and maintenance.

C.A.

BS020	Rev. No.:1	Original Issue Date: 1/10/08 Revision Date: 1/10/08 <small>All bulletin services must be printed and attached to the manuals. Celier Aviation can not be held responsible for the use or the misuse of the bulletin service system.</small>
--------------	-------------------	--