

Bulletin Service Mandatory

Bulletin Service Mandatory for all Xenon models until 05/2009 ; for the fuel tank breaving hoses. Originally they are mounted in the engine compartment over one tube of the engine support. With time and heat they tend to skeeze, blocking the air in & out of the tanks. It is requested to re-route it as per the photo shown here. The spring act to keep correct shape and curve radius of the hose.If you cannot find this spring on the general market, it is available at our factory.

